



1



2



3



4



5

Area 2

This area is **not closed**. Photo 1 shows access from ATV trail at road segment 3523. This is also accessible by all vehicles at road segment 1919. Invasive species are present primarily garlic mustard. These road are mostly below grade native silt soil surface the east side is generally dryer with some sand surface, the west side of this area having generally all silt soils. The east side is suitable for light traffic . Recommend no through traffic restriction on east side. The west side is not suitable for traffic with the last harvesting operation in this area had significant difficulty maintaining road 1914 and 811. Recommend full closure of 1914 and 811. All road segments are currently accessible by vehicle.

Photo Locations Area 2

